



External Dimension


Unit: mm



Mounting Dimensions



Terminal Assignments



1	OUTPUT-1	(+)
2	OUTPUT-1	(-)
3	N.C.	
4	INPUT	(100%)
5	INPUT	(CENTER)
6	INPUT	(0%)
7	SUPPLY	(L+)
8	SUPPLY	(N-)
9	GND	(GND)
10	OUTPUT-2	(+)
11	OUTPUT-2	(-)